
	SB-A500A-0210-02	Revision: --
		Type: EA 400
Model: EA 400-500		
Project: A500A-22-05		
Date: 13. Sep. 2023		
Design Organisation EASA.21J.551		

SERVICE BULLETIN

MM UPDATE

Contents

1. Subject	3
2. Affected Aircraft	3
3. Introduction	3
4. Compliance	3
5. Approval	3
6. Instructions for continued airworthiness	3
7. Effectivity date	3
8. Installation check-out log	4
8.1. Continued airworthiness data	5
8.2. A/C Documentation checks	5
8.3. Installation accomplishment statement.....	5

 EASA.21J.551	SB-A500A-0210-02 MM UPDATE	Rev.:	--
			13. Sep. 2023

1. Subject

This service bulletin introduces changes which affect the aircraft maintenance manuals for both the EA400 as well as the EA400-500 with respect to the landing gear, its hydraulic system and related components replacement time limits.

2. Affected Aircraft

All EA400 (Extra 400) series and EA400-500 (Extra 500) series.

3. Introduction

The updates of the maintenance manuals are:

- Harmonisation of the EA400 and the EA400-500 maintenance instructions with respect to landing gear and hydraulic system as well as consideration of-service experience.
- Changes to components replacement time limits.

4. Compliance

New maintenance manuals are available through SST's customer support department, for contact details refer to chapter 8.

5. Approval

"The technical content of this document is approved under EASA TC Change Approval 10082680."


6. Instructions for continued airworthiness

The following manuals have been updated and shall be used for future maintenance:

- EA400 Maintenance Manual MM-EA400-0210-01 **Issue 1-0**
- EA400-500 Maintenance Manual MM-A500-A-0210-01 **Issue 1-0**

7. Effectivity date

This SB becomes effective at the date of issuance.

 EASA.21J.551	SB-A500A-0210-02	Rev.:	--
	MM UPDATE	13. Sep. 2023	

8. Installation check-out log

Submit a signed copy of the following page to:

support@sst-flugtechnik.com

SST FLUGTECHNIK GmbH
tel. +49-8331-972980
Am Flughafen 12a
D-87766 Memmingerberg

If problems with the implementation of this Service Bulletin occur, please contact SST-Flugtechnik by the contact details above.

For occurrence reporting refer to

<https://eccairsportal.jrc.ec.europa.eu/index.php?id=2>

and

<http://www.aviationreporting.eu/AviationReporting/>

and SST directly:

[Occurrence Report - SST Flugtechnik \(sst-flugtechnik.com\)](http://www.sst-flugtechnik.com)

8.1. Continued airworthiness data

INSTALLING AGENCY		AIRCRAFT OWNER	
Name:		Name:	
Organisation No.:		Postal Address:	
Contact Person:			
Postal Address:		Telephone No.:	
		E-Mail:	
Telephone No.:		MODIFIED AIRCRAFT	
E-Mail:		Aircraft Type:	
Date of installation:		Aircraft Model:	
		Serial Number:	
		Registration:	

8.2. A/C Documentation checks

MM(S) MM(S) completed and inserted.

8.3. Installation accomplishment statement

I hereby confirm

- that all conditions and requirements set forth in this Service Bulletin are met;
- that the installation and check-out instructions of this Service Bulletin have been followed;
- that the information provided in this check-out log is complete and correct.

Date

Name in block letters

Signature